



US Army Corps of Engineers
Northwestern Division



An Overview of the Risks of PCBs at US Army Corps of Engineers Hydropower Projects in the Columbia Basin

Paul Ocker - NWD

Ken Duncan - NWP

July 30, 2009



US Army Corps of Engineers Northwestern Division



- Overview
 - Gathering Data at the request of EPA
 - For the purpose of this presentation, focus on the Lower Columbia
- Potential Sources of Oils and PCB materials
- Risk and risk reduction
- Recent history
 - Bonneville Dam – Bradford Island
 - The Dalles Dam – Transformer Spill of 2004



US Army Corps of Engineers Northwestern Division



Quick History

- PCB's were first manufactured commercially in 1929 , as a “safer” cooling and insulating fluid for industrial transformers and capacitors.
- PCBs were widely used in a variety of electrical equipment because they do not conduct electricity easily and are not very flammable.
- PCBs were often used in oils, paint, chlorinated rubbers, plastics, sealants and caulking, adhesives, glues and tapes

PCBs at Corps of Engineers - FCRPS Dams

- PCBs were historically used in transformer oils and other electrical equipment
- In 1969, upon recognizing the need to reduce the risks for PCBs, the Corps began removal of PCB equipment and/or fluids from the dams.



US Army Corps of Engineers Northwestern Division





Oil at FCRPS Hydropower Projects

- The 3 largest sources of oil at FCRPS hydropower projects include:
 - Turbines
 - Kaplan (up to 7,000 gallons per unit)
 - Francis (Up to 4,000 gallons per unit)
 - Turbine Oil Storage Rooms (up to 200,000 gallons per dam)
 - HV Transformer Oil (6,000 - 16,000 gallons per unit)
- Measures in place to contain oil
- TSCA Categories of equipment
 - > 500 ppm = PCB Equipment
 - 50-500 ppm = PCB Contaminated
 - 1-49 ppm = Non-PCB



US Army Corps of Engineers Northwestern Division



Reportable Spills for the FCRPS 2008

Date	Spill	Location	Probable Cause	To Water	Extent
22-Jan-08	Turbine Oil	Lower Monumental Dam	Turbine bearing maintenance	179	600 gallons total, likely 179 to the river
3-Oct-08	Turbine Oil	Dworshak Dam	turbine bearing cooler	80	Max potential of 500 gallons
1-Nov-08	Hyd Oil	The Dalles Dam	Underwater Drilling Equipment	77	70-77 Gallons to the river, most contained
5-Feb-08	Turbine Oil	The Dalles Dam	Turbine unit 21	25	approximately 25 gallons
24-Apr-08	Boat Fuel	Bonneville Dam	Capsized Boat	19.99	less than 20 gallons
17-Jan-08	Turbine Oil	The Dalles Dam	Turbine bearing oil filter failure	14.99	less than 15 gallons to the river
17-Mar-08	Gas and Oil	Dworshak Dam	Sunken boat	9.99	Less than 10 gallons of gasoline and oil
26-Nov-08	Hyd Oil	Ice Harbor Dam	Tainter Valve Leak	6	Cracked Weld
18-Oct-08	Turbine Oil	Ice Harbor Dam	Overfill of Turbine Unit	5	5 gallons to the water
27-Mar-08	Hyd Oil	McNary Dam	Fish Screen Motor	<1	Less than 5 gallons
27-May-08	Oil	Bonneville Dam	Spillway Gate Hoist	<1	less than 1 gallon
27-Mar-08	Oil	Lower Monumental Dam	RSW Installation	<1	Approximately 1 quart
17-Mar-08	Oil	Bonneville Dam	Boat exhaust	<1	Unknown - Sheen was observed
31-Mar-08	Oil	Foster Dam	Crane Leak	<1	1 cup of hydraulic oil
18-Nov-08	Hyd Oil	The Dalles Dam	Underwater Drilling Equipment	<1	Less than 1Gallon to the river, most contained
1-Oct-08	Oil	Chief Joseph Dam	Sump pumped	<1	~2-3 ounces to the river
1-Mar-08	Oil	Bonneville Dam	Crane may have leaked oil	<1	Teaspoon or less
26-Sep-08	Hyd Oil	Chief Joseph Dam	Broken Seal - Leased Crane	<1	~1 QT to the deck - 0 to the water
20-Nov-08	Grease	Lookpoint Dam	Spillway grease leaked	<1	Grease melted onto deck, rain washed in
21-Nov-08	Lube	Big Bend Dam	Replaced equipment?	<1	Sheen reported but very light
2-Dec-08	Oil	Little Goose Dam	Construction Activity	<1	Unknown sheen
15-Dec-08	Oil	The Dalles Dam	Construction Activity	<1	Less than 1Gallon to the river, most contained




Walkthrough of Bonneville Dam PH1 Turbines



10 Turbine Units at Bonneville Powerhouse 1
Total Volume of Oil for Governors and Hub = ~ 160,000 gallons
Concentration of PCBs = 0ppm




Walkthrough Of Bonneville Dam PH 1 Oil Storage



9 Oil Storage Tanks
Total Volume of Oil Stored = ~85,000 gallons
Concentration of PCBs = 0ppm



Walkthrough Of Bonneville Dam Large Transformers



5 Transformer Banks with 3 phases at Bonneville Powerhouse 1

Total Volume of Oil for Transformers = ~ 80,000 gallons

Concentration of PCBs = Nondetected (at 2ppm level) as tested 1995-2006



US Army Corps of Engineers Northwestern Division



The Dalles Dam		
Transformers Tested in 2003	Detected Levels of PCBs	
	(Detection Limit = 2ppm)	
2638-1	ND	
2638-2	ND	
2638-3	ND	
2638-4	2	
7023790	9	Replaced 2005-06
7023791	8	Replaced 2005-06
7023792	5	Replaced 2005-06
140791	ND	
140792	ND	
140793	ND	
140794	ND	
140795	ND	
140796	ND	
140797	ND	
140798	ND	
140799	ND	


140800	ND	
140801	ND	
140802	ND	
140803	ND	
140804	ND	
140804	ND	
140806	3	
140807	3	
140808	2	
H409355	ND	
H409356	ND	
H409357	ND	
H409358	ND	
6948659	ND	
6948659	ND	



US Army Corps of Engineers Northwestern Division



High Voltage Bushings





High Voltage Bushings and PCBs

- Bonneville 1 (Completed 1938)
 - Bushings were replaced in the 1980's (Stamped <1ppm PCB on nameplate)
- Bonneville 2 (Completed 1982)
 - Not all Bushings are “known” for concentrations
 - Spare bushings (Stamped <1ppm PCB on nameplate)
- The Dalles (Completed 1960)
 - All bushings presumed to have a concentration of greater than 50ppm
- John Day (Completed 1971)
 - A small number were tested and determined to have a concentration of 125ppm, therefore all (13) are assumed to be <125 ppm.
- Bushings may contain (up to) a gallon of oil



Other Potential Sources of Oils or PCBs at FCRPS Dams

- Other Electricity-Generating Equipment
 - Breaker boxes, Electric vaults, Capacitors, Switches, Etc...
- Non Electricity-Generating Equipment
 - Light Ballasts (~7500 lbs eliminated since 2002)
 - Small Transformers ~100 gallons or less
 - Navigation Lock switches and hydraulics
 - Spillway gate hoists or switches
- Some has been tested, some have not,
- Most suspected and tested equipment has not contained any PCBs



Some Unknowns

- **Paints**
 - Paints manufactured up to about 1975
 - Presently we do not suspect an issue
 - Unknown in the FCRPS
 - 1 known instance occurred in Omaha District
- **Caulks**
 - Used in some buildings from the 1950s through the 1970s.
 - Unknown in the FCRPS



Bottom Line for Current Operations

- Are Corps Hydropower Dams “PCB Free”?
 - No, however:
 - Large oil sources at dams are not regulated as *PCB equipment*
 - Very low or no concentrations
 - Much has been removed
- Does the Corps “know” where all of the “*PCB containing equipment*” might be at Hydropower dams?
 - No, however:
 - We have a good idea where most of it is
 - Any remaining is in small volumes and is typically stable or well contained
 - We assume it is PCB where it is unclear
- Do current operations at Corps Hydropower Dams pose a significant risk of PCB releases?
 - No



Presently Working with EPA

- PCB Equipment at the dams
 - In Use
 - In Storage
- Other PCB containing materials
- Activities to further identify and mitigate any PCB sources



Recent History of PCBs

- Bonneville / Bradford Island CERCLA* Site

* Comprehensive Environmental Response, Compensation and Liability Act



TECHNICAL ADVISORY GROUP

OR Department of Environmental Quality
Tribal (Umatilla, Yakama, Nez Perce, Grand Ronde,
Warm Springs and Cowlitz)
Columbia River Inter-Tribal Fish Commission
US Fish & Wildlife Service
National Marine Fisheries Service
Bonneville Power Administration
Corps of Engineers (Seattle, Portland)



US Army Corps of Engineers
Waters and Hydraulics Division



Bonneville Dam

Robbins Island

1st Powerhouse

**Bradford
Island**

Spillway

Cascade Island

BRZ

2nd Powerhouse


BUILDING STRONG®



US Army Corps of Engineers Northwestern Division



Area of discovered PCBs at Bradford Island





US Army Corps of Engineers Northwestern Division



ELECTRICAL EQUIPMENT REMOVED in 2002




LDING STRONG



US Army Corps of Engineers Northwestern Division



SEDIMENT REMOVAL in 2007





US Army Corps of Engineers Northwestern Division



FILTERING BARGES




DIVING BARGE



US Army Corps of Engineers Northwestern Division



- **2000 Nov – Discovery of Capacitors in water**
- **2002 Feb – Removal of in-water equipment**
- **2007 – Completed in-water cleanup**
- **2008 – Completed Remedial Investigation Sampling**
- *2009 – Remedial Investigation Report*
 - *Complete Analysis of Samples*
 - *Complete Data Sufficiency Reports*
- **2010 – Complete RI Report and Risk Assessment**
- **2011 - Feasibility Study and Record of decision (ROD)**
- **2012 – Design of clean-up (remedial) actions**
- **2013 – Implement actions**



Reference
Sampling Area

Cascade Locks

Columbia River

Forebay
Sampling Area

Cascades Island

Bonneville Dam
and Spillway

Bradford Island

Robins Island

Bonneville


North
Bonneville

Hamilton Island

Ives Island

Pierce Island

Downstream Sampling Area





US Army Corps of Engineers Northwestern Division



Total PCB Aroclor Data in Post Removal Samples

	Sediment	Clam	Crayfish	Smallmouth Bass (congener data)
Forebay	19 samples 17 non-detect 2 detections ≤ 27 ppb (dry)	19 samples 18 samples ≤ 30 ppb 1 sample 120 ppb (wet)	17 samples all non-detect	Presently being analyzed
Reference	18 samples all non-detect	18 samples detected in all samples 31 to 39 ppb (wet)	19 samples all non-detect	19 samples detected in 7 analyzed 22 to 164 ppb (wet)
Eagle Creek Sediment	2 samples 1 non-detect 1 detection of 76 ppb (dry)	--	--	--
Downstream Sediment	6 samples all non-detect	--	--	--




The Dalles Transformer Spill

- What happened:
 - Transformer failed, oil escaped secondary containment through expansion joints
 - Multi-Agency response, recover actions



The Dalles Transformer Spill

- January 2004
- 1303 gallons of oil spilled
 - 638 gallons recovered
 - 665 gallons unrecovered
- 8.0 ppm PCB





The Dalles Transformer Spill

- What happened since then:
 - Replaced Transformer (T2)
 - All transformer secondary containment is intact and inspected regularly



Bottom Line for Historic Operations

- We occasionally “discover” PCB related issues
- Proactive in fixing issues when we find them