

INSPECTION AND PREVENTIVE MAINTENANCE REPORT
(Complete Once Every 3 Months)

Facility Name: SHELLEY BAP
Inspector Name: STEPHEN R. GOODSON
Date: AUG. 27, 2019
Weather Conditions: CLEAR / HOT

Are any of the following observed?

<u>Yes</u>	<u>No</u>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Corroded or damaged tanks, tank supports, and/or tank drain valves.
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Torn bags exposed to rainwater.
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Torn or leaking bags in baghouses (packaging room).
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Corroded or leaking pipes.
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Leaking or improperly closed valves and valve fittings.
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Leaking pumps and/or hose connections.
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Broken or cracked dikes, walls, or other physical barriers designed to prevent stormwater from reaching stored materials.
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Buildup of process materials in areas exposed to stormwater.
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Windblown dry materials.

Debris, sediments, product in the following storm sewer drains:

<input type="checkbox"/>	<input checked="" type="checkbox"/>	5 yard drains in main parking lot
<input type="checkbox"/>	<input checked="" type="checkbox"/>	2 yard drains in pallet yard east of Packaging Building
<input type="checkbox"/>	<input checked="" type="checkbox"/>	4 yard drains north of Warehouse A (next to building)
<input type="checkbox"/>	<input checked="" type="checkbox"/>	1 yard drain north of Granules Bulk Storage Building
<input type="checkbox"/>	<input checked="" type="checkbox"/>	1 yard drain south of Warehouse B

INSPECTION AND PREVENTIVE MAINTENANCE REPORT
(Complete Once Every 3 Months)

- ___ ☒ 1 yard drain in on north side of Kingston Produce
- ___ ☒ 1 yard drain south of Scale House (next to road)
- ___ ☒ 1 yard drain south of Cellars #7 and #8 (paved area)
- ___ ☒ 2 yard drains on both sides of road north of Quonset Bldg.
- ___ ☒ 1 yard drain on southwest corner of fence surrounding Secondary Waste Treatment Area/ south of road.
- ___ ☒ Truck Scale drains (Scale House)
-
- ___ ☒ 2 curb drains on east side of Plant (Emerson Street)
- ___ ☒ 2 curb drains on south side of Plant (both sides of Fir Street)
-
- ___ ☒ 2 roof drains on Bulk Storage Area
- ___ ☒ All roof drains on Main Plant
- ___ ☒ All roof drains on Storage Cellars
- ___ ☒ All roof drains on Food Service and Raw Materials Warehouse

Is spill response equipment still available and in operable condition? ☒ Yes ☐ No

If no, identify deficiencies: _____

INSPECTION AND PREVENTIVE MAINTENANCE REPORT
(Complete Once Every 3 Months)

SITE INSPECTION OBSERVATIONS

Observation	Responsible Personnel	Action Taken	Date Repaired or Completed