

Routine Facility Inspection

2019

June 6, 2019 – Q2

Lamb Weston, Inc.
TWIN FALLS

**856 Russet Street
P.O. Box 128
Twin Falls, Idaho 83301-0128**

Telephone (208) 733-5664

Dry/Wet Inspection
(circle one)

Routine Facility Inspection (Quarterly)

This Routine Facility Inspection Report is written in accordance with section 3.1 of the Multi Sector General Permit (MSGP).

3.1 Routine Facility Inspection Procedures

Conduct routine facility inspection of all areas of the facility where industrial materials or activities are potentially exposed to storm water, and of all storm water control measures used to comply with the effluent limits of this permit. Due to the low risk of storm water contamination, routine facility inspections must be conducted at the Twin Falls facility quarterly (i.e., once each calendar quarter). Inspections must be performed when the facility is in operation. You must specify the relevant inspection schedules in your SWPPP document as required in Part 5.2.5.2. These routine inspections must be performed by qualified personnel with at least one member of your storm water pollution prevention team participating.

NOTE: Per the MSGP permit at least once a calendar year the routine facility inspection must be conducted during a period when a storm water discharge is occurring. If a discharge does not occur the Environmental Manager must notify EPA of such until a variance to the sampling requirement can be obtained.

3.1.2 Routine Facility Inspection Documentation

You must document the findings of each routine facility inspection performed and maintain this documentation onsite with your SWPPP. **You are not required to submit your routine facility inspection findings to EPA**, unless specifically requested to do so. At a minimum, your documentation of each routine facility inspection must include:

- The inspection date and time;
- The name(s) and signature(s) of the inspector(s);
- Weather information;
- All observations relating to the implementation of control measures at the facility, including:
 - A description of any discharges occurring at the time of the inspection;
 - Any previously unidentified discharges from and/or pollutants at the site;
 - Any evidence of, or the potential for, pollutants entering the drainage system;
 - Observations regarding the physical condition of and around all outfalls, including any flow dissipation devices, and evidence of pollutants in discharges and/or the receiving water;
 - Any control measures needing maintenance, repairs, or replacement;
- Any additional control measures needed to comply with the permit requirements;
- Any incidents of noncompliance; and
- A statement, signed and certified in accordance with Appendix B, Subsection 11.

Inspection Date: 10-10-19 Time of Inspection: 7:30 AM - 11:00 AM

Name of inspectors:

TODD KIRKENDALL

Signature

Signature

Signature

Signature

Signature

“I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information contained therein. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information contained is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.”

Paula

Plant Manager

6/6/15

Date

Weather Information (See recorded data from Joslin Field)

http://www.wunderground.com/history/airport/KTWF/2013/3/29/DailyHistory.html?req_city=NA&req_state=NA&req_statename=NA

Time	Temperature	Dew Point	Humidity	Wind	Wind Speed	Precip.	Precip. Accum
6:53 AM	75 F	51 F	43 %	ENE	5 mph	0.0 in	0.0 in
7:53 AM	79 F	51 F	38 %	NNE	7 mph	0.0 in	0.0 in
8:53 AM	80 F	51 F	36 %	E	6 mph	0.0 in	0.0 in
9:53 AM	83 F	49 F	31 %	N	3 mph	0.0 in	0.0 in
10:53 AM	82 F	47 F	29 %	W	5 mph	0.0 in	0.0 in
11:53 AM	83 F	37 F	19 %	WSW	22 mph	0.0 in	0.0 in

Describe any discharges at the time of the inspection.

NONE. There hasn't been a discharge from the plant for several years.

Any previous unidentified discharges from and/or pollutants at the site?

No Yes If yes, describe:

Any evidence of, or the potential for, pollutants entering the drainage system?

No Yes If yes, describe:

Identified several opportunities for improvement that are underway now and should be completed by next week (see attachments).

State observations regarding the physical condition of and around all outfalls (1,3,5, and 8), catch basins and containment pond, and evidence of pollutants in discharges and/or Rock Creek:

Sand bag rolls on West side of pond will need to be repositioned this summer. Catch Basins will need to be cleaned when they dry out. All outfalls are in great shape and clean. Zero evidence of pollutants in any outfalls.

Any control measures needing maintenance, repairs, or replacement?

No Yes If yes, describe:

Minor stuff. See attachments.

Any additional control measures needed to comply with the permit requirements?

No Yes If yes, describe:

Any incidents of noncompliance observed or known?

No Yes If yes, describe:

Kirkendall, Todd

From: Kirkendall, Todd
Sent: Friday, June 7, 2019 8:48 AM
To: Main, Chad
Subject: SWPPP Inspection Action Items

Hi Chad,

As discussed during the Q2 SWPPP inspection yesterday I discovered a few opportunities.

Please have Josh address the following next week.

#1) grab the two unopened bags of salt at Outfall #3 and the partial pallet in the metals recycling area behind maintenance and place in the starch warehouse.
#2) Replace/clean/repair filter screens on intakes for UIC system servicing area outside of the forklift shop.

Thanks!

Todd Kirkendall
Sr. Manager – Environmental
856 Russet Street | Twin Falls, ID 83301
t 208.736.5643 | m 208.252.0069
Todd.Kirkendall@lambweston.com

CONFIDENTIALITY NOTICE:

This message and any attachments are solely for the use of the individual or entity to which this message is addressed and contains information that is confidential. If the reader of this message is not the intended recipient, you are hereby notified that any review, re-transmission, disclosure, copying, distribution or the taking of any action in reliance on the contents of this communication by persons or entities other than the intended recipient is strictly prohibited. If you have received this message in error, please contact the sender and delete the material from any computer.

Kirkendall, Todd

From: Kirkendall, Todd
Sent: Friday, June 7, 2019 8:55 AM
To: Dingman, Tim
Cc: Haman, Tony
Subject: Action Items from SWPPP Inspection

Hi Tim,

Completed the Q2 SWPPP inspection yesterday and identified a few opportunities.

- 1) The tote outside by L2 Fryer used to capture roof runoff is almost overflowing. Could you please have it emptied?
- 2) On the railroad tracks near the tote mentioned above we have what looks to be dried potato skins that needs to be cleaned up. I think it could be easily scrapped into a pile and scooped into a trash can with a flat head shovel.

Other than that everything looked fantastic.

Thanks for your help Tim!

Todd Kirkendall
Sr. Manager – Environmental
856 Russet Street | Twin Falls, ID 83301
t 208.736.5643 | m 208.252.0069
Todd.Kirkendall@lambweston.com

CONFIDENTIALITY NOTICE:

This message and any attachments are solely for the use of the individual or entity to which this message is addressed and contains information that is confidential. If the reader of this message is not the intended recipient, you are hereby notified that any review, re-transmission, disclosure, copying, distribution or the taking of any action in reliance on the contents of this communication by persons or entities other than the intended recipient is strictly prohibited. If you have received this message in error, please contact the sender and delete the material from any computer.

Kirkendall, Todd

From: Kirkendall, Todd
Sent: Friday, June 7, 2019 9:09 AM
To: Phillips, Joseph
Subject: Environmental Action Item

Hi Joe,

Completed the Q2 SWPPP inspection yesterday. Noticed two barrel containment pallets outside just West of the compressor room are 90% full.

Could you have someone on your team empty them in the near future?

Appreciated!

Todd Kirkendall
Sr. Manager – Environmental
856 Russet Street | Twin Falls, ID 83301
t 208.736.5643 | m 208.252.0069
Todd.Kirkendall@lambweston.com

CONFIDENTIALITY NOTICE:

This message and any attachments are solely for the use of the individual or entity to which this message is addressed and contains information that is confidential. If the reader of this message is not the intended recipient, you are hereby notified that any review, re-transmission, disclosure, copying, distribution or the taking of any action in reliance on the contents of this communication by persons or entities other than the intended recipient is strictly prohibited. If you have received this message in error, please contact the sender and delete the material from any computer.