



ARCADIS U.S., Inc.
695 North Legacy Ridge Drive
Suite 200
Liberty Lake
Washington 99019
Tel 509 929 3369
Fax 509 928 3075

MEMO

To:

Eric Winiecki/EPA
Rene Fuentes/EPA
Jennifer MacDonald/EPA

Copies:

Henry Bosma/Liberty Dairy
Patrick Ryan/Perkins Coie

From:

Kevin Freeman/ARCADIS

Date:

April 18, 2013

ARCADIS Project No.:

Sk030326.0001

Subject:

Administrative Order on Consent (SDWA-10-2013-0080) – Liberty Dairy, LLC and its associated Dairy Facility H&S Bosma Dairy, Backflow Prevention Devices

This memorandum was prepared to serve as documentation of Liberty Dairy, LLC, and its associated Dairy Facility H&S Bosma Dairy, compliance with requirements for backflow prevention devices contained in the Administrative Order on Consent (AOC) (SDWA-10-2013-0080) Scope of Work (SOW) Section III.F.5. SOW Section III.F.5 states:

“Backflow Prevention System – Within 30 days of the Effective Date, Respondents shall install and maintain backflow prevention devices to protect all wells at the Dairy Facilities.”

Table 1 presents a summary of wells at Liberty Dairy and H&S Bosma Dairy and the backflow prevention devices associated with each well. Photographs of the backflow prevention devices at Liberty Dairy and H&S Bosma Dairy are also included as an attachment to this memorandum.

Table 1 – Liberty Dairy and H&S Bosma Dairy Backflow Prevention Device Inventory

Well	Manufacturer/Model	Serial Number
<p>Liberty Dairy</p> <p>East Parlor Well</p> <p>Pen 5 Well</p> <p>(Wells report to same service manifold)</p>	<p>Watts Model 909JA1</p>	<p>No serial number plate on device</p>
<p>H&S Bosma Dairy</p> <p>Inside Well</p> <p>Outside Well</p> <p>(Wells report to same service manifold)</p>	<p>Wilkins Zurn Model 375</p>	<p>L80627</p>

H&S Bosma Dairy



Liberty Dairy

