

20. 11. 81 au

Air



sec. 4
Ref. 5




Source Category Survey: Animal Feed Dryers

MRI-N.C. OFFICE
LIBRARY COPY

AP-42 Section 9.9.1
Reference 10
Report Sect. _____
Reference _____

Note: This is a reference cited in *AP 42, Compilation of Air Pollutant Emission Factors, Volume I Stationary Point and Area Sources*. AP42 is located on the EPA web site at www.epa.gov/ttn/chief/ap42/

The file name refers to the reference number, the AP42 chapter and section. The file name "ref02_c01s02.pdf" would mean the reference is from AP42 chapter 1 section 2. The reference may be from a previous version of the section and no longer cited. The primary source should always be checked.



EPA-450/3-81-017

Source Category Survey: Animal Feed Dryers

Emission Standards and Engineering Division

Contract No. 68-02-3059

U.S. ENVIRONMENTAL PROTECTION AGENCY
Office of Air, Noise, and Radiation
Office of Air Quality Planning and Standards
Research Triangle Park, North Carolina 27711

December 1981

This report has been reviewed by the Emission Standards and Engineering Division, Office of Air Quality Planning and Standards, Office of Air, Noise and Radiation, Environmental Protection Agency, and approved for publication. Mention of company or product names does not constitute endorsement by EPA. Copies are available free of charge to Federal employees, current contractors and grantees, and non-profit organizations - as supplies permit - from the Library Services Office, MD-35, Environmental Protection Agency, Research Triangle Park, NC 27711; or may be obtained, for a fee, from the National Technical Information Service, 5285 Port Royal Road, Springfield, VA 22161.

Publication No. EPA-450/3-81-017

TABLE OF CONTENTS

	<u>Page</u>
List of Figures	iv
List of Tables	iv
CHAPTER 1. SUMMARY	1-1
1.1 Background	1-1
1.2 Industry and Process Description	1-3
1.3 Industry Growth and Emissions	1-5
1.4 References	1-7
CHAPTER 2. INTRODUCTION	2-1
CHAPTER 3. SURVEY CONCLUSIONS	
3.1 Industry Growth	3-1
3.2 Availability of Control Technoly	3-1
3.3 Significant Emission Sources	3-3
3.4 Availability of Emission Data	3-3
3.5 Applicable Methods for Sampling and Analysis	3-3
CHAPTER 4. DESCRIPTION OF INDUSTRIES	4-1
4.1 Animal Feed Dryers Description	4-1
4.2 Source Category	4-2
4.3 References	4-28
CHAPTER 5. AIR EMISSIONS DEVELOPED IN SOURCE CATEGORY	5-1
5.1 Plant and Process Emissions	5-1
5.2 Total National Emissions From Source Category	5-1
5.3 References	5-4
CHAPTER 6. EMISSION CONTROL SYSTEMS	6-1
6.1 Control Approaches	6-1
6.2 Best Systems of Emission Reduction	6-5
6.3 References	6-5
CHAPTER 7. EMISSION DATA	7-1
7.1 Availability of Data	7-1
7.2 Sample Collection and Analysis	7-1
7.3 References	7-1
CHAPTER 8. STATE AND LOCAL EMISSIONS REGULATIONS	8-1
8.1 Summary of Emission Regulations	8-1
8.2 References	8-2
Appendix A	A-1

LIST OF FIGURES

	<u>Page</u>
Figure 4-1. Soybean Oil Mill Processing Plant Flow Diagram . . .	4-8
Figure 4-2. Wet Corn Milling Plant Flow Diagram	4-11
Figure 4-3. Dry Pet Food Manufacturing Flow Diagram	4-13
Figure 4-4. Beet Sugar Processing Flow Diagram	4-16
Figure 4-5. Alfalfa Dehydrating Plant Flow Diagram	4-18
Figure 4-6. Fish Meal Plant Flow Diagram	4-21
Figure 4-7. Feather Meal Plant Flow Diagram	4-23
Figure 4-8. Distilled Spirits Plant Flow Diagram	4-25
Figure 4-9. Malt Beverages Plant Flow Diagram	4-27

LIST OF TABLES

	<u>Page</u>
Table 1-1. Source Category Summary	1-2
Table 2-1. Industries and Products	2-2
Table 2-2. List of Plants Visited	2-4
Table 3-1. Source Category Growth Projections	3-2
Table 4-1. List of Contacts	4-4
Table 5-1. Summary of Emission Factors Developed from Test and Permit Data	5-2
Table 5-2. Summary of National Particulate Matter Emissions by Industry	5-3
Table 6-1. Control Devices Used on Emissions from Animal Feed Dryers by SIC Code	6-2
Table 7-1. Emission Test Data	7-2
Table 8-1. Summary of State Air Pollution Regulations	8-3